

Figure 1

Stage 1: Initial Cavity Formation

Fishre 2

Injection Well






Figure 3




Cavity Formation across Shale Partings

Stage 2:

Stage 3: Tubing Pull-Back or Perforation to Extend Cavity





Cross Section

Plan View